

Ctrl+2	User interface preferences
Ctrl+o	Open file
Ctrl+s	Save the workpart. If the workpart is an assembly, all changed components will be saved too.
Ctrl+Shift+a	Save file as
Ctrl+m	Switch to modeling .
Ctrl+Shift+m	Switch to sheet metal .
Ctrl+Shift+d	Switch to drafting .
F8	Aligns the view. If planar surfaces are selected in the graphics window, the view is aligned to this surface.
F5	Refresh view
Ctrl+f	Fit view to screen
w	Shows or hides the coloured CSYS.
F4	Repeat last command
Ctrl+z	Undoes last command
Ctrl+y	Executes the previously undone command again
x	extrude
alt	Suppress snapmode in sketcher
Ctrl	If you hold down the Ctrl key, selected objects in the sketcher are copied when you move them with the mouse.
Ctrl+d	Delete
Ctrl+L	Layer settings
Ctrl+j	Edit object display (after class selection)
Ctrl+e	Expressions
Ctrl+b	Hides selected objects.
Ctrl+Shift+b	Toggles the display between hidden and displayed objects.
Ctrl+Shift+k	Shows selected objects again
Ctrl+Shift+u	Show all
Ctrl+w	Show and hide
Ctrl+1	Customize
List keyboard shortcuts	Press Ctrl+1 and click on Keyboard in the shortcuts tab. then click on Report in the window that appears.
Create your own keyboard shortcuts	Press Ctrl+1 and click on Keyboard in the shortcuts tab. Select a category in the upper left area and select a command in the upper right area. In the lower right area, enter the desired key combination and click on Assign.